

637

Now, this is one of the posts that is being erected underneath that undercrossing that you looked at a moment ago. The rail here again was up on top of a curb and it is, as you see, put in without washers. And it was none too high at this point.

