


This again is a closeup view of twin bridges, rather close together. And again the lack of anchorage between the rail and the structure. This is repeated over and over.

This rail up on top of a curb, of course, would not function as well as one that was clear.

Here is the type of hole that you drop into at this particular location. You can see the fence, anchor fence, up here at the top, and the ends of the two rails, with the daylight between all the way around.



This is another structure showing the attempt here at anchorage. This is the one I thought I had before. But in this case, the rail

