


bridge; it is completely unprotected. Aside from this reflectorized marker, which with the black stripes down, Mr. Ricker said, means you keep on this side.

Another approach on that same bridge where there is a slight overlap, 6-foot, 3-inch post spacing used here indicating there is recogni-



tion of the need for stronger rail support in this area. This again is a commendable step.

Not fully adequate. Similar situation.

