


You can see the remains of the base. This is so constructed and wired that the pole breaks away at the base. Here are remnants of these little clip sections that go on the bottom. And the wiring is such that there is an automatic disconnect when the pole is knocked down.



Here is a closeup of the pole after it was hit, presumably an impact about bumper height, as you can see. And the pole is broken away here at the base.

