


This is another picture of an outside post being hit. The driver went to sleep, and I might point out that that post is approximately 25 feet from the edge of the travelway. At that point I might read, if I may, from some of the accident reports. We now have 69 of them documented.



Accident No. 69, the last one we documented, says—

The vehicle left the road 425 feet in advance of the sign, struck the support and returned to the pavement 150 feet beyond the sign.

There was no report of the accident. The maintenance people found the sign in a damaged condition and repaired it.

No. 59—

Leaving the roadway, the vehicle struck the right support at a 15° to 20° angle. Tracks continued diagonally across the ditch and onto the frontage road.

No. 58—

The vehicle was returning to the roadway at a 15° to 20° angle and struck the left support of the sign.