


1074

This is the base of the support.



This vehicle hit the luminaire almost exactly the same way as the fatal accident that Dr. Rowan showed. It hit broadside and as you will notice, at such speed that the pole came over the top, but there was no injury to the occupants or the driver.

