

1179

Here is another installation in Salt Lake where the guardrail misses coming to the end of the bridge by some 8 or 10 feet. It is enough to drive between without touching either the bridge or the guardrail.



This is a concrete headwall and drainage structure placed directly off the inside shoulder.

