

Mr. W. MAY. Again they have installed one, two, three different types of barriers because of this median, because of this construction of the bridge.

Mr. BRIDWELL. They wanted to make sure, Mr. May.


Mr. W. MAY. I am sure. That represents real hazardous location the way it exists.

Perhaps they could level that concrete parapet or median barrier and carry the cable barrier through the structure and remove this small piece of guardrail we see in the right. Again, the Bureau would participate in this?

Mr. TURNER. I would think it should.

Mr. W. MAY. What do you think of my suggested correction?

Mr. TURNER. That would be one I would want to look at.



Mr. W. MAY. This is a typical sign installation right along the shoulder. Again, if that sign were to be moved elsewhere, the Bureau would participate?

