


And I guess another similar type problem. These could be at least placed on breakaway supports.

Mr. TURNER. They should be placed on wooden posts that would break when hit.



Mr. W. MAY. Apparently those guardrail installations were designed to protect the motorist from striking the center pier, and it appears it won't quite do it, but this could be corrected easily with not too much expense.

