


This is another bridge which carries the shoulders through the structure. No transition from the guardrail, in this case to a concrete parapet bridge railing.



On the newest project here they used a new standard to upgrade their work. You find that they used here a rather nice aluminum bridge railing which appears to be effective from the tests. But again we have no transition from the guardrail to the bridge rail, and at the point of transition we still have remaining that ever-present concrete parapet at the end of the bridge.

Does that have to be there, Mr. Turner, that concrete parapet?

