

LATHES (con't)TYPE

Automatic Screw Machine,					
Bar, Horizontal, 2 Spindle			2" Bar & over		5
"	"	4 Spindle	4" - 6" Bar cap.		1
"	"	"	6" Bar & over		1
"	"	8	under 1 1/2" Bar cap.		11
"	"	"	1 1/2" - 2" " "		9
"	"	"	2" Bar & over		9
Automatic Chucking Lathe					
N/C					12