Barr Labs.

Meprobamate Tablets, USP.

Major Deficiencies

3. Lack of a dust control system.

Collected powder present on overhead beams and tops of other manufacturing equipment such as dryers and ovens.

4. No record on verification of regular cleaning of equipment and no documentation to assure that drug residues have been removed to avoid cross contamination.