#### 10536 COMPETITIVE PROBLEMS IN THE DRUG INDUSTRY

Date

### Conditions found

# Nov. 1967

Seven deviations from GMPs including the following four critical deviations:

- -- No assay of raw materials.
- -- No controls over labeling.
- -- No manufacturing records other than master formula.
- --Lot numbers not assigned to batches.

Also, firm did not clean bottles or caps used in packaging and did not have equipment to clean them.

## Mar. 1968

Inspection revealed no changes in firm's operations; owner made no effort to comply with previous inspector's oral recommendations. Eight deviations from GMPs were identified, including the following four critical deviations:

- --No assay of raw materials.
  --No working formulas.
  --No manufacturing records.
  --No label controls.

# Sept. 1969

No improvements in manufacturing practices. Six deviations noted, two critical:

- -- No assay of raw materials or finished products.
- -- No manufacturing records.

Also, failure to adequately clean packaging and labeling equipment.

# June 1971

by the act. Thirteen violations of GMPs were identified, five critical:

- -- No master production and control records.
- -- No batch production and control records.
- -- No laboratory control.
- -- No stability testing of finished product.
- -- Lot distribution could not be readily determined.

#### FDA action

Deviations discussed with representative of firm. Reinspection was scheduled for March 1968.

No listing of inspectional ob-servations was issued. Post inspection letter issued 40 days after inspection.

Letter did not cite any vio-lation of the FD&C Act. No response was requested or received. Reinspection was scheduled for Catober 1968, but was not made until Septem-ber 1969.

A list of inspectional observa-tions was issued. Post inspec-tion letter was issued 22 days after the inspection. Response was requested but not received. Reinspection was scheduled for March 1970 but not made until June 1971.

A list of inspectional observations was previded. No pest inspection letter was issued. Reinspection was to be scheduled, but no further action was taken as of December 31, 1971.