

11970 COMPETITIVE PROBLEMS IN THE DRUG INDUSTRY

RECALL NUMBER	PRODUCT	LOT(S)	MFR. & RECALLER	REASON	TYPE	CLASS	OTC or Rx
D-278-4	Mercurydrin Injection 10cc multiple dose vials or 1 N. & S.C. use and 1cc & 2 cc ampules for IM, IV & S.C. use	all	Mfr & Recaller: Lakeside Labs Div. Colgate Palmolive Milwaukee, Wisc.	Unidentified precipitate	Vol.	II	Rx
D-280-4	H.P. Acthar Gel (ACTH Repository Corticotropin 40 USP units per ml)	1	Armour Pharmaceuticals Co., Kankakee, Ill.	Subpotency	Vol.	II	Rx
D-282-4	Magnesium Sulfate Injection	1	Mfr: Abbott Labs Rocky Mount, N.C. Recaller: Abbott Labs N.Chicago, Ill.	Labeling incorrect - front panel label on boxes of 25 ampules incorrectly stated ...4mEq. This should have read 8 mEq... All other labeling correct.	Vol.	II	Rx
D-284-4	Surgical Simplex P. Radiopaque Bone Cement	1	Mfr: North Hill Plastic Ltd., London, England Recaller: Howmedica Inc. Medical Division Rutherford, N.J.	Product contains foreign particulate matter	Vol.	II	Rx
D-287-4	Quinidine Sulfate 0.2 gm. tablets	1	Mfr & Recaller: Cenci Labs Inc. Fresno, Calif.	Subpotency	Vol.	II	Rx
D-288-4	Labtubes (A10450 Defect Report)	4	Abbott Scientific Products Div. Abbott Labs, Inc. South Pasadena, Calif.	Calcium contamination which would result in errors in clinical determinations if the tubes were used for blood analyses	Vol.	II	Rx