


And here on the right you can see it would be very possible to put this sign stanchion on top of the wall or behind the wall, and clear this shoulder area.

I want you to notice that 50-mile-an-hour sign, because in the next slide it will be down.



Mr. BLATNIK. Is this the same sign?

Mr. LINKO. This is before and after.

I took pictures in advance of about 150 places which later were hit, because I knew the installations were wrong and dangerous. I tried to bring this to the attention of officials but nobody would listen.

