

When Mr. Kopecky came down to see me, we noticed this condition. The light was down and the mark is on that second offset.

We took a look at the car which is farther down, and this is what we saw.



He did not get that from knocking down the light post.



And here is another shot of the same thing showing the glass was broken; somebody went through it.