


Here you see they eliminated all the bridge abutments, but they put concrete stumps in the center here under the light poles. This is wrong. You have a low curb and somebody can cross over and have a head-on crash, and if they hit these light posts, they are in trouble.



This would be the proper way of doing it. Why not build a barrier and have no maintenance at all on your light posts?

