

Here is another gore area that is clear but it has been overrun.



This is the front view of the previous slide. There was an accident and the light pole was knocked down and a temporary pole put back, instead of removing the light and putting it inside the center guard-rail. This ramp in the gore is an expensive thing, and this actually could tip you over.

