


Here you can see it is all busted up, so he must have hit it pretty hard.

This is not really necessary. It is not even the curb at all; the curb is here at the right so why can't we guide that car past, give him the 10-foot shoulder.



And here is another one; this is new work.

