

Here, also, you see an easy knocked down pole with 24 feet of guardrail, and if you look farther down to where the spot is on the bridge abutment, there is where we need the guardrail; here it is creating a hazard.

