

Here you see they are in the process of relighting our highways which probably happens every 20 or 30 years. I feel they are doing it wrong, because from all the books I have managed to grab hold of and read, they say these lights should be put beyond the shoulder—that means about 10 feet—and 2 feet beyond. Here you see they are not putting them back 10 feet in the center.



It should be done in a manner like this, giving you plenty of room to go by.

I will point out again that maybe it took us 20, 30 years to relight that other highway and we are doing it wrong.

These lights are constantly being knocked down, because of the way they are being put in. I feel if the Government has anything to do with this they should not pay for this job.

