Here you can slide along there and it is impossible to hit the end of the opposite rail. They could have done the same thing at the other location, but no one was thinking.



Most of our highways are in this condition. You leave the road, slide along the guardrail, and you have run into the end of the next section of guardrail.

And this has been hit; sort of standard practice on highways in our

area.

