

And when I was reviewing the police accident records, I found that there had been an accident at this very location. The driver of this car, a young sailor, was killed. His vehicle got up on the embankment and hit just one of the sign supports, this 8-inch I-beam.

