




Mr. ZION. Mr. Prisk, in this last slide, the rail is not blocked out. It looks as though it is low enough that a wheel wouldn't go below the W-beam. Is that correct?

Mr. PRISK. That is right. This rail was about 25 inches, if I recall correctly, on this particular project; 25 inches was their mounting height. So you would—

