


This was field changed during the construction, and work, I expect, now is completed. It was under way as we visited the project.

We move along on this section. This is about the way it looks as those portions are completed. The rail is taken down a slope, both in the median and on the right-hand side.



Here is a case where you have a gap and somebody put the flare in on the wrong end, because you are driving in the same direction as the camera is looking and there is a nice waterhole straight ahead, if you follow that flare, that you could drop into, up in this general area here [indicating].

