

Mr. PRISK. Square posts and wood blocks.

Here you do see that muddy area between the edge of the shoulder and the rail, makes you wonder a little bit whether that rail would perform as well as if it had a paved surface coming up to the face of it. When it is soft, certainly the wheel would be down somewhat lower than it would otherwise.

