


Did I understand you correctly?

Mr. WILSON. That is correct.

Mr. PRISK. So if your exit signs are standing up, I would say this is too heavy; no question about it.

Mr. RICKER. The exit sign I believe has $27\frac{1}{2}$ square feet of area, so the wood post is perfectly adequate to hold it up.

Mr. PRISK. Moving back to our favorite sign, which you saw a moment ago, this gore I think speaks for itself, after what we have said about it previously.



There are not too many things in here that are necessary. It could be entirely cleared by an advance sign bridge 200 feet to the right of the picture, and the rest of the gore is fairly flat, negotiable, traversable by car.

This is a view from the back of the same sign, only to indicate that the gore is not any problem of itself.

