

see that it is not totally outside the range of possibility of running through here, taking the sign out and running through here and coming to rest down below without getting into any great difficulties.

We have some trees down there. There is always something you can hit, of course, if you go far enough.

Mr. CONSTANDY. Before that project is completed, it is probable that there will be more fill put in that gore; is that correct?

Mr. PRISK. Right there at the beginning; yes.

That previous shot (slide) this one here, of course, that will be filled to curb height, we expect, in front of the sign.

In back of the sign, shown by this next picture, I have no way of knowing if anything is going to be done there.

Mr. CONSTANDY. What I am wondering about, when that fill is added, in this particular one at least, it would seem that the concrete footings of the sign would then not project above the grade quite so much.

Mr. PRISK. I think that is true.

