

And this continuation is on the same section. Side slopes are also a little steeper.



Now we move to Missouri, and we run into high fills of this type.



There is no guardrail put in on this project at all yet, and I think you can see that easing the slope in this kind of country is a rather substantial job, but at the same time it presents a substantial hazard.

