

Many thanks for the new sign. If it had been one of the old type, we undoubtedly would have gone through the windshield or turned over. As it was, no injury resulted to my self or friend.

The automobile received only \$500 damage, and by the way, most of this was caused by hitting a 2-inch pipe in a secondary collision.

This is a sign that was impacted in a hit-and-run accident. You will note that the angle of departure from the roadway to the sign caused it to strike the outside leg of the support.



This is an accident showing the inside leg of the support struck by a truck. This particular driver went to sleep. There were no injuries or injury, type C. This was "no visible sign of injury," but there was complaint of pain. One hundred and fifty dollars' damage to the truck, \$125 damage to the sign.

