

Mr. TURNER. Yes. That sign should either be moved back up on the slopes there where it cannot be hit, or it should be moved to some other location. It is not essential that you put that distance to destination sign at exactly those mileposts. It could be 2 miles, 3 miles, or 17 miles; it would make little difference.

Mr. W. MAY. Yes, sir.

That is a similar type problem.

