



Here is the same sign mounted on the right on a pole, eliminating all maintenance and putting it in a more favorable position, a little higher, and at no extra cost.

Mr. W. MAY. Mr. Linko, to go back one (fig. 1-009) at one time there was another sign on the left pointing toward the oncoming traffic?

Mr. LINKO. Yes. One on the right and one on the left.

Mr. W. MAY. Both have been hit?

Mr. LINKO. Yes. If that had been on the light pole in the background, it would take these right out of the shoulder altogether, and there would be no maintenance at all, and it would have saved a fortune of money in the original installation.

Now, these are not small poles. They may look small; they are 2½-by 3-inch angle irons. If you hit them, you may get into serious trouble.

