

And you can see somebody smashed into this concrete base. Many accidents have occurred here. Notice that the guard rail is gone—it was hit and it went down. The guardrail has been damaged and removed at this particular location. It's been like this for over 2 years and nobody wants to take the responsibility for replacing it.



This is the same location. You see snow on the ground. There is still no guardrail.

