

And here you see a guardrail installed wrong on the right-hand side. In the center barrier they had an excuse; they called it a center barrier so let's say the guy put it there. But here there is not any reason for this guardrail at all. The only reason it is there is to protect the bridge abutment. You can see it is guiding you right into the bridge abutment.



If you look close, you can see a scratch all along there, where a bumper hit this. They repaired it and put it right in the same place. This is wrong.

