

Mr. W. MAY. They did not put a bridge and post on this one.

Mr. LINKO. No, but that can cut you in half, too, because it is set back.

Mr. W. MAY. Yes.



Mr. LINKO. Here is a case where they removed the high curb, but the guardrail is set behind the bridge abutment, you see.

Now you have the material to do the job properly, but it is not installed properly, so all these unnecessary accidents at these points are really not necessary.

Now here you see the guardrail set in front of the curb allowing you to go right through.

