

But this is what you will see on all highways. This is Interstate 95 and this is only a pedestrian bridge, a narrow bridge, and yet you see the standard.



If that was not bad enough, here you have a situation where some water was leaking out of the rocks, and during a couple of months of a year it used to freeze and create a hazard; so they sent some people over here to eliminate the hazard. What they did was build these two concrete walls to keep the water from leaking out. Before, we had a

