


Now, this is a brand new section of an interstate highway. Here on the left the guardrail is installed wrong because you can slide right into the abutment. Notice there are three structures in this one picture.



Here is a close-up view of something we were just talking about. You see the fence in between there; the material is there to provide a smooth-sliding action. Someone wasn't thinking; there is a tapered curb there and there happens to be a little turn, and because of that someone is going to have to get wiped out in that spot.

