


The light pole also had been knocked down but they replaced it before I took this picture.



They put an easy-knockdown sign there, but they failed to remove the guardrail in the rear which is laying on the ground.

