

Mr. MAY. They will never get to it, because they will smash into that concrete pedestal?

Mr. LINKO. This is right. I would like to point out this is Interstate. I think we should get some maintenance.

Mr. CRAMER. There is another example of those light posts going up the ramp, constituting a hazard, when they could just as easily be put on the wall. Is there any reason why those lampposts could not be put on the wall?

Mr. PRISK. No, sir.



Mr. LINKO. Here also you see a new sign just installed and there is a concrete stanchion there between the legs. Nobody thinks of removing it. This is an easy-knock-down sign. It (the stanchion) is not serving any purpose at all.

Here also you see a sign knocked down two 2 years ago and the stanchions are still there. A small sign has since been put in.

