

Here you see they did put it here. This is a proper sign installation. But even here they did a half job, because the guardrail protecting this sign that is behind the fence is 2 feet from the curb. It is hard to see. There is a spot there pointing it out. You could run into that thing and wreck your car and it is not even protecting the sign.

Mr. MAY. So we understand, that sign support is behind the fence?

Mr. LINKO. That is right.

Mr. MAY. They have put up that hunk of guardrail to protect—what is the reason?

Mr. LINKO. I do not see any reason. That can smash the car, and it is not protecting anything.



This points out, whether entrance gore areas or exits, they should be off limits to everything. If you could put this sign in advance, up there like I have marked.

