

Another hazard, which is supposed to be a protective device. This is a tight right-hand curve, which is a feeder road to one of the expressways, and in the background—actually, up above off of the screen, you see the chain-link fencing between the pine pillars. They went off the road, hit this, and this led them on a collision course directly to the tree.

