

Another example of hazards close to the road. This happens to be one we had of a salesman driving home one night from Ann Arbor when he came off this crest of the road. Notice the characteristic of the road edge here. It is very badly chewed up. His wheel got off on this area. He tried to bring the car back to the roadway, but he went down the steep embankment, as we can see by the tracks in the distance, and

