

This is what we found one night. Two college students were traveling on this expressway when they hit the end of that guardrail. This car is now 144 feet into the guardrail. There are 144 feet behind them from where they first hit that guardrail. And so we have to think of protecting the ends of those guardrails.

I recommend a sloping end buried firmly into the ground to prevent this type of accident from occurring.

The passenger was killed.



This is the front view of the car.

