


Here you see another place where somebody ran right through. You can look at the tree branches that broke off. I feel they made a serious mistake using this type of material on an Interstate highway. If cars can go through, so can trucks and buses, and you can have a disaster.

I feel we have an obligation and go back and strengthen these points as soon as possible before a gasoline truck or something goes through these railings.



This is another aluminum installation. You can see it just snaps right off.

