


And here is a patched-up job where they put a section in there. Take a closeup look and you can see how they put it together. They are not even fastened. Kick it and it goes off.



And here is another place that was struck and the rail gave way. There is a street below.

