


This is another aluminum installation. Nobody hit this particular installation. From expansion and contraction, this particular railing worked its way right out of the ground.



Here is another section here.

