

Here I would like to point out that this is a section of the aluminum railing I have been showing you. You can see one of these uprights has snapped completely off. There is not a mark on that railing. That means it could not have been hit hard. Aluminum alloy is not a strong alloy, so what they do is they temper it. In tempering it to make it hard, they also make it like glass. So if you just tap it, it just snaps right off. That is what happened here.

