




Here is a wood railing protecting on a bridge. A car ran right through, as these two pictures show, and went into the water there and the driver drowned.



Here they are hoisting the car up. Take a close look at this wooden railing—this can't hold back moving cars. And these are in many dangerous places in heavy traffic. Also, you can see it is rotting away and it's not being maintained.