




The three foregoing pictures show that under the right conditions something could fall on the windshield of cars below and even cause a four- or five-car accident.

This covers some aluminum W-beams. I feel we made a serious mistake using this type of material. I favored aluminum before when I talked about use of it on our light poles and bases. I told you it had no strength and it snaps off and does no damage. That is exactly what it is doing here; it is snapping off.

