


This is the same location; there was no sliding action, it broke off and they got all that damage.



Here you can see where somebody came through also. The broken guardrail is pointing toward you, and that is a double rail. These are only cars coming through here, not trucks. This on an interstate highway.

